



**TEL-TRU  
MANUFACTURING CO.**  
*World-Class Instruments*  
Thermometers • Pressure Gauges • Transmitters • Accessories

---

**TEL-TRU CHECK-TEMP CALIBRATOR  
PACKING INSTRUCTIONS**

---

# **IMPORTANT!**

- Please keep the original carton and packing materials for re-certification service returns.
- Carefully pack your calibrator when shipping it back for re-certification service (see page 2).
- At the top of re-cert purchase receipt you will find a six-digit order number, which you will need for shipping. This is your Check-Temp Re-certification Reference number (CR). Please clearly mark this number in the format "**CR XXXXXX**" on the outside of the shipping carton.
- Ship to:       Tel-Tru Manufacturing Co.  
                    408 St. Paul Street  
                    Rochester, NY 14605

**Tel-Tru Manufacturing Company**

MAIN OFFICE: 408 Saint Paul Street, Rochester, New York 14605

MAILING ADDRESS: PO Box 30144, Rochester, New York 14603-3144 USA

Phone: 585.232.1440 • 800.232.5335 • Fax: 585.232.3857 • E-mail: [info@teltru.com](mailto:info@teltru.com) • Web: [www.teltru.com](http://www.teltru.com)

QUALITY PRODUCTS SINCE 1916

Effective 3/2/11  
96100076W

**CALIBRATOR PACKING INSTRUCTIONS FIGURE 1**

